

The technical drawing illustrates the assembly of a wooden cabinet, divided into three main sections:

- Parts List (Налични елементи):** Located at the top left, it lists components A through S. A separate diagram shows the assembly of a corner joint using parts G, H, I, J, K, and L.
- Assembly Steps:**
 - Step 1:** Shows a hammer driving a nail into a board.
 - Step 2:** Shows a screw being driven into a board.
 - Step 3:** Shows a screw being driven into a board.
- Exploded View:** The main part of the drawing shows the exploded view of the cabinet. It includes:
 - Top (М таван):** The upper horizontal panel.
 - Back (N гръб):** The rear vertical panel.
 - Sides (О страница, Р страница):** The left and right vertical panels.
 - Bottom (Q дъно):** The lower horizontal panel.
 - Door (чекмедже):** The front panel, shown with internal components I, J, K, L, M, N, O, P, Q, R, S, T, U, V, W, X, Y, Z.

